

Date: Friday, 17/10/2008 2:43:42 PM  
User: Linda Lacelle

# Process Sheet

<b>Customer</b> : CC-DAR01 Dart Aerospace Ltd.	<b>Drawing Name</b> : D3560-2 / -3
<b>Job Number</b> : 42736	
<b>Estimate Number</b> : 10804	
<b>P.O. Number</b> :	<b>Part Number</b> : SCRAP30
<b>This Issue</b> : 17/10/2008 <b>S.O. No.</b> :	<b>Drawing Number</b> : SCRAP
<b>Prsht Rev.</b> : NC	<b>Project Number</b> :
<b>First Issue</b> : / / <b>Type</b> : MACHINED PARTS	<b>Drawing Revision</b> :
<b>Previous Run</b> : 00015	<b>Material</b> :
<b>Written By</b> :	<b>Due Date</b> : 24/10/2008 <b>Qty:</b> 1 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> :	
<b>Comment</b> :	

## Additional Product

Job Number:



<b>Seq. #:</b>	<b>Machine Or Operation:</b>	<b>Description :</b>
----------------	------------------------------	----------------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



**Comment:** PACKAGING RESOURCE #1

PULL FROM STOCK:

1 X D3560-2 B30538  
1 X D3560-3 B31507

2.0	D35602	Arm
-----	--------	-----



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)  
Arm

*Ep 08/10/28* (Signature)

3.0	D35603	Arm
-----	--------	-----



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)  
Arm

*Ep 08/10/28* (Signature)

4.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------



**Comment:** SMALL & MEDIUM FAB RESOURCE 1

SCRAP/DESTROY PARTS  
(OLD STYLE, NO LONGER USED)

*Ep 08/10/28* (Signature)

5.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



**Comment:** FINAL INSPECTION/W/O RELEASE

*08/10/29* (Signature)

*11 08/10/29* (Signature)

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

